

Date: 4 March 2002

STATEMENT OF WORK  
For the  
Inspect and Repair Only As Necessary (IROAN)  
Of the  
Light Armored Vehicle (LAV-25)  
Thermal Sight System  
Post Amplifier Circuit Card Assembly  
NSN 5998-01-438-5452

SOW-04-PM-LAV-8H734B-2/1

1. No Statement Of Work (SOW) is required to IROAN the Post Amplifier CCA, NSN 5998-01-438-5452, Part Number 6245994. The Marine Corps lack the necessary technical data for repair, and the technical data is proprietary to the Original Equipment Manufacturer (OEM). This is a commercially repaired item that has to be returned to the OEM.

2. The following points of contact apply:

Randy Geoghagan  
Equipment Specialist  
Program Manager  
Light Armored Vehicles-Albany  
MARCORSYSCOM, Albany, Ga.

Carolyn Mayberry  
Inventory Management Specialist  
Supply Chain Management Center  
Combat Ground Weapons Branch Code 576-3  
MARCORLOGBASES, Albany, Ga.